
REPUBLIC OF LEBANON


Ministry of Public Works & Transport
Directorate General of
Land & Maritime Transport











То:	International Maritime Organization	From:	A.H. Kayssi
			Director General of Land and
			Maritime Transport
Fax	+44(0)207587 3210	Fax:	+961 1 371647
Pages:	6 (including this one)	Date:	25.11.2013
Subject:	"M/V RHOSUS" IMO:8630344	Our Re:	
	Inspection in accordance with Med		
	MOU		*

NOTIFICATION OF DETENTION OF SHIP

Dear Sirs,

In accordance with the provisions of Section 3.6.3 and 3.7 of the Med MOU on port state control.

The port state control office of Lebanon has on 25.11.2013 carried out an inspection of the above ship at the port of BEIRUT

The ship was detained due to the following detainable deficiencies:

- 1- Echo sounder: not working properly.
- 2- Inmarsat c: out of order
- 3- Safety shoes: missing.
- 4- Cleanliness of engine room: dirty.

5-Jacketed high pressure lines: not as required

Please find enclosed a copy of the report of inspection forms A&B and the notice of detention for the Master.


Reporting Authority: Directorate General of Land and Maritime Transport

Name: Mr Tony Assaf
On behalf of Director General of Land and Maritime Transport

Signature:

Ministry of Public Works & Transport Directorate General of Land & Maritime Transport







То:	Ministry of Transport and Road Industry	From:	A.H. Kayssi
			Director General of Land and
	127 222 251 122		Maritime Transport
Fax &	+37 322 251 123	Fax:	+961 1 371647
E-mail	Admin.nav.moldova@gmail.com		
Pages:	6 (including this one)	Date:	25/11/2013
Subject:	"M/V RHOSUS" IMO:8630344	Our Re:	
	Inspection in accordance with Med		
	MOU		

NOTIFICATION OF DETENTION OF SHIP

Dear Sirs,

In accordance with the provisions of Section 3.6.3 and 3.7 of the Med MOU on port state control.

The port state control office of Lebanon has on 25.011.2013 carried out an inspection of the above ship at the port of BEIRUT

The ship was detained due to the following detainable deficiencies:

- 1- Echo sounder: not working properly.
- 2- Inmarsat c: out of order3- Safety shoes: missing.
- 4- Cleanliness of engine room: dirty.
- 5- Jacketed high pressure lines: not as required.

Please find enclosed a copy of the report of inspection forms A&B and the notice of detention for the Master.

Reporting Authority: Directorate General of Land and Maritime Transport

Name: Mr Tony Assaf
On behalf of Director General of Land and Maritime Transport

Signature: